IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No .:

7.887.664 B1

Docket:

127-P-105USU1

Issue Date:

February 15, 2011

Patentee:

John D. Mata et al.

Title:

CONTINUOUS MOLDED EMITTER

NOTICE OF ERRORS IN PRINTED PATENT

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

The following errors were noted in the above-identified issued patent:

Column 1, Line 39: "As higher speeds," should read -- At higher speed, --.

Column 1, Line 42: "...path will loose its..." should read --...path will lose its...-.

 $\label{eq:column2} Column\ 2, Line\ 25: "... through the inlet and exists through..." should read\ -- through the inlet and exists through...-.$

Column 3, Line 13: "Existing flow paths..." should read -- Exiting flow paths...-.

A Certificate of Correction is not believed warranted in this case, but the errors are hereby made of record for the benefit of anyone reading the file of the issued patent.

Respectfully submitted,

JOHN D. MATA ET AL.

Date: 3 -2/- //

By: Michael L. Mau Reg. No.: 30,087

IPLM Group, P.A. Post Office Box 18455 Minneapolis, MN 55418 Telephone (612) 331-7415

MLM:lam